

THERE WAS NO AI ACTIVITY ON 3215. ONLY ONE SIGNAL WAS RECORDED.

THIS SIGNAL UP FROM 0232-0244Z AND WAS FROM TOKEN RADAR FEEDING THOUGH

FROM S BAND. SIGNAL HAD FOLLOWING PAR: 345 PPS-19.1 SPR INTERCEPTED

FROM LEFT SIDE. X BAND WAS SLIGHTLY NOISY AND THIS COULD POSSIBLE

HAVE TRIGGERED SYSTEM IX.

END OF MESSAGE

25 YEAR RE-REVIEW

SECRET Congression of the second congression

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED.